







CUTTING-SYSTEMS



CUTTING-SYSTEMS



A. 2x	E. 1x	I. 2x	M8x16: 20x	M8: 16x
B. 2x	F. 1x	J. 1x	M8x12: 4x	M8: 4x
C. 4x	G. 1x	K. 2x	M8x50: 4x	M8: 8x
D. 2x	H. 4x	L. 2x	M8x60: 4x	

CUTTING-SYSTEMS



CUTTING-SYSTEMS

